

## Announcement - New Optima Firmware Release (Version 2.02)

Hi everyone,

Please be informed that Hitec have released a firmware update for Optima 7 & 9 receivers.

Hitec strongly advise all its customers to update their receivers at their earliest convenience, especially when used in situations which may generate excessive electrical noise, such as:

- Spark ignition engines, or
- High powered brushless motor setups.

You will find detailed information on the Hitec USA website.

This is the link:

<http://www.hitecrd.com/support/firmup/spec24update.html>

Optima Receiver Firmware **Version 2.02** – Released October 7, 2011

- Improved reboot function
- Improved noise rejection capabilities.

It is important to keep your equipment up-to date to benefit from Hitec's commitment to maintain industry leading features and performance.

Thank you for your attention.

**Best Regards,**

**Colin Lee**

**Hitec RCD Korea,Inc.**

